UNSTARRED QUESTIONS AND ANSWERS.

Amount spent by the P.W.D. on each of the Minor and Major Tanks in Magadi Taluk since 1959.

Q.—116. Sri C. R. RANGE GOWDA (Magadi).—

Will the Government be pleased to state :—

the amount spent by the P.W.D. on each of the Minor and Major tanks in Magadi Taluk for the repair of channels, sluices, feeder channels and tank bunds since 1959 ?

A.—Sri ALUR HANUMANTHAPPA (Deputy Minister for Minor Irrigation).—

A statement is appended.

STATEMENT.

Showing the expenditure incurred in respect of each Major and Minor Tanks in Magadi Taluk for repairs to channels, sluices, tank bunds since 1959. (*Vide* reply to U. S. L. A. Question No. 116).

Name of work	1959-60	1960-61	1961-62	1962-63
1	2	3	4	5
	Rs.	Rs.	Rs.	Rs.
1 Strengthening the bund of Chivinkere Tank, Magadi Taluk ...	Nil	2,409	...	...
2 Do Kalyanapura Tank, Solur Hobli ...	,,	1,465	...	...
3 Urgent repairs to sluice to the leaky sluice in Grade 31 of Kempsagara Minor Tank..	,,	600	...	...
4 Restoring Chikkalur Tank, Register No, 324 of Magadi Taluk ...	,,	...	6,539	1,085
5 Balance works of Sankighatta Tank, Magadi Taluk.	,,	1,622	11,446	1,225
6 Do for putting earthern jackbund in the tank bed of Kannasandra Voddarakatte S. No.26, Kudur Hobli ...	,,	1,566	...	...

1	2	3	4	5
	Rs.	Rs.	Rs.	Rs.
7 Restoration of Koramangala Kodagikere ...	"	...	16,370	...
8 Do of breached kaleri kaval tank ...	"	...	2,732	...
9 Strengthening to central grade of Doddamudigere Tank ...	"	...	2,397	...
10 Constructing wasteweir to Shantipura Tank, Solur Hobli ...	"	...	2,405	...
11 Strengthening the bund of Thavarekere Doddakere ...	"	...	...	15,125
12 Improving the channel of Chakrabavi Tank ...	"	...	2,900	...
13 Restoration of Sulvara Tank, Tavarekere Hobli ...	"	...	13,772	...
14 Strengthening the bund of Chandigi Begur kath of Sugganahally ...	Nil	...	1,415	...
15 Closing the leaks in 4, 6th grades of Shantipura Tank...	"	...	...	1,111
16 Construction of new waste weir body wall to the Banigere Tank right side Thippasandra Hobli ...	"	...	...	5,312
17 Restoration of Channamanahally Valankere, Thavarekere Hobli. ...	"	...	...	1,360
18 Turfing the slopes of bund in grades 15,16,31,32, Narasandra Major Tank ...	"	...	...	520
19 Improvements to wasteweir of Gudemaranahally Chikkere of Magadi Taluk ...	"	...	...	1,680
20 Closing the leak of Koramargala kodagikere ...	"	...	...	2,335
21 Restoration of Hebbalalu Tank ...	"	...	18,404	14,619
22 Restoration of draft channel wasteweir Halla of Hebbalalu Tank ...	"	...	...	2,335
23 Restoration of Katti in S. No. 31 of Thirmale village...	"	...	...	2,990

1	2	3	4	5
	Rs.	Rs.	Rs.	Rs.
24 Strengthening the remaining grades of bund and closing the breach portion of Thavarakere Doddakere ...	,,	...	...	7,251
25 Narasandra Tank ...	2,900	863	900	...
26 Chelur Tank ...	1,350	332	572	...
27 Chiksolur Tank ...	...	450	1,500	...
28 Marur Surappanakatte ...	1,030	941	...	1,107
29 Veerapura Tank ...	...	...	...	1,947
30 Alur Doddakere ...	...	...	...	629
31 Thattikere Tank ...	1,000	...	1,000	...
32 Thippasandra Major Tank...	...	...	646	...
33 Aralikatte Tank ...	1,502	...	....	...
34 Kempasagara Katti ...	2,225	1,400	...	...
35 Solur Major Tank ...	506	459	...	1,476
36 Byladakere Tank ...	...	140	4,241	1,745
37 Doddamudigere Tank ...	...	420		...
38 Beeravara Hosakere ...	...	...	900	...
39 Kalyanpura Tank ...	650	...	...	..
40 Thammenahalli Tank ...	750	...	..	...
41 Thubinakere Tank ...	..	238	...	1,550
42 Ombathanakunte Tank ...	...	230	...	1,287
43 Gudemarnahalli Chikere ...	...	...	...	3,526
44 Ajjanahalli Puttanakatte ...	476	325	967	1,321
45 Sankhighatta Tank ...	....	...	...	2,121
46 Ganakal Tank ...	...	68	...	...
47 Hulikal Hirikere ...	...	554	...	...
48 Basavahalli Tank ...	...	924	...	1,746
49 Kannasandra Sorekatte	144	...	...	...
50 Gourammana Tank ...	880	...	...	300
51 Shantapura Tank ...	925	...	2,000	...
52 Mofaganahalli Tank ...	...	...	2,425	2,811
53 Rangenahalli Tank ...	...	...	...	2,079
54 Hulikatte Mogekere ...	...	838	1,900	4,873
55 Kenchanahalli Tank ...	1,290	...	...	...
56 Kenkenahalli Tank ...	637	...	...	...
57 Chakrabhavi Tank ...	637	...	...	...
58 Herthi Tank ...	320	...	991	...
59 Belagumba Tank ...	3,400	...	...	...
60 Ranojpalya Tank ...	650	...	...	...
61 Chandurayanahalli Tank ...	650	...	...	...

1	2	3	4	5
	Rs.	Rs.	Rs.	Rs.
62 Juttanahalli Tank ...	915	...	...	...
63 Thaggikuppe Hosakere ...	2,225	...	...	...
64 Adarangi Kalasanakatte ...	...	...	762	...
65 Mathikere Doddakere ...	...	...	1,250	...
66 Agalkath Sankaraswarankere...	5,050	...	3,200	...
67 Sugganahalli Kenkere ...	1,737	...	...	1,1[illegible]7
68 Baganikere Tank ...	...	420	512	...
69 Udukunte Tank ...	402	355	...	586
70 Chikkaiya Tank ...	...	791	...	1,080
71 Patandiah Katte ...	...	1,033	...	...
72 Hosahalli Chikkere ...	...	243	...	...
73 Honnapur Tank ...	...	...	...	1,893

Grant for the Construction of Houses at Bovi Colony in Gudlahally, Madabal Hobli, Magadi Taluk.

Q.—134. Sri C. R. RANGE GOWDA (Magadi).—

Will the Government be pleased to state :—

(*a*) the total number of houses for the construction of which loan and grant were given to Bovi Colony in Gudlahally, Madabal Hobli of Magadi Taluk (the amount granted to each of them may be furnished) ;

(*b*) the number of houses completed ;

(*c*) the amount required to complete these incomplete houses ?

A.—Sri D. DEVARAJ URS (Minister for Labour, Housing and Transport).—

(*a*) No grant has been sanctioned to Bovi Colony in Gudlahally, Madabal Hobli, Magadi Taluk, but only loan has been given for the construction of sixty-one houses (Statement appended).

(*b*) 13

(*c*) Rs. 30,500.